X16B SAFETY CHECKLIST				1	BROOKHAVEN NATIONAL LABORATORY NATIONAL SYNCHROTRON LIGHT SOURCE
Rev: A	Effective: 6/12/06		Page 1 of 1		Number: LS-SCL-0035
Reviewed by:	Thomas McDonald	Reviewed by	y:		Approved by: A. Ackerman

Original signatures on file.

The only official copy of this file is the one on-line in the NSLS Quality Assurance website. Before using a printed copy, verify that it is the most current version by checking the document effective date on the NSLS QA website.

	1. Valid Padlock Index and log, no locks open
	2. Exclusion Zone (EZ # 1) in place and secure.
	3. Bremsstrahlung Shielding (BS # 1) banded and secure.
	4. Exclusion Zone (EZ # 2) in place and secure from BS # 1 to EZ # 3.
	5. Exclusion Zone (EZ # 3) in place and secure.
	6. Bremsstrahlung Shielding (BS # 2) banded and secure.
	7. View ports (5) covered with lead plates.
	8. Exclusion Zone (EZ # 4) in place and secure.
	9. Bremsstrahlung Shielding (BS # 3) banded and secure.
	10. Exclusion Zone (EZ # 5) in place and secure.
	11. Exclusion Zone (EZ # 6) in place and secure just upstream of X16C hutch.
	12. Exclusion Zone (EZ # 7) in place and secure inside X16C hutch
	13. Bremsstrahlung Shielding (BS # 4) in place and secure.
	14. Exclusion Zone (EZ # 8) in place and secure from BS #4 to BS #5.
	15. Bremsstrahlung Shielding (BS # 5) banded and secure.
	16. Exclusion Zone (EZ # 9) in place and secure.
	17. Exclusion Zone (EZ # 10) in place and secure.
	18. View port covered with leaded glass.
	19. Scatter shielding on beamline components as per photo.
	20. Exclusion Zone (EZ # 11) in place and secure.
	21. Bremsstrahlung Shielding (BS # 6) banded and secure.
	User System Checks
	A. Water is flowing to all water-cooled components (6 green lights on user interlock panel)
	B. Adequate vacuum throughout beamline (1 green light on user interlock panel)
Cl	hecked by:
	OPCO: